

24 DEC 1964

PRIORITY

OUT 4733

P 232305Z
FM NPIC WASHDC
TO RUEAHQ/DIA WASHDC
INFO RUEPIA/CIA WASHDC
BT
S E C R E T//CITE NPIC 3553.

SUBJECT: FILM EVALUATION MISSION T324A.

1. CAMERA C-120 WAS EMPLOYED IN MISSION T324A FLOWN 17 DEC-
EMBER 1964.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MINOR ROLLER INDUCED STATIC DISCHARGES (ROLLER
CHATTER) ARE PRESENT INTERMITTENTLY ON THE OUTBOARD (TITLED)
EDGE OF THE FILM.

C. 9L SIDE: FRAMES 1832-1838 CONTAIN AN IRREGULAR PLUS
DENSITY STREAK APPROXIMATELY 1" INBOARD AND ROUGHLY PARALLEL TO
THE EDGE OF THE FILM. SIMILAR STREAKS APPEAR INTERMITTENTLY IN
SUBSEQUENT FRAMES.

D. BOTH SIDES: FRAME 001 IS SEVERELY DEGRADED BY IMAGE
MOTION. THE OUTBOARD EDGES CONTAIN MINOR EDGE STATIC DISCHARGES.
THE COUNTER MALFUNCTIONED ON COUNTER NUMBER 2196 (JUMPED FROM
2195 TO 2197) BUT RESUMED NORMAL OPERATION THEREAFTER. THE
TITLED FRAMES ARE NUMBERED 0001-2176.

3. DUPLICATE POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. THE CLOUD COVER IS 25 PERCENT, CONCENTRATED PRIMARILY
TOWARDS END OF MISSION. GP-1.

S E C R E T

-END OF MESSAGE-

SECRET

COPIES RECEIVED			
CyNo.	Office	Act.	Rec'd
23	23	24	7
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
29			
30			
31			
32			
33			
34			
35			
36			
37			
38			
39			
40			
41			
42			
43			
44			
45			
46			
47			
48			
49			
50			
51			
52			
53			
54			
55			
56			
57			
58			
59			
60			
61			
62			
63			
64			
65			
66			
67			
68			
69			
70			
71			
72			
73			
74			
75			
76			
77			
78			
79			
80			
81			
82			
83			
84			
85			
86			
87			
88			
89			
90			
91			
92			
93			
94			
95			
96			
97			
98			
99			
100			

GROUP 1
Excluded from automatic
downgrading and
declassification